AUB 1 1 1890

SAM-SON Inspection and Technical

License No. 34-25898-01

Services, Inc.

ATTN: Mr. S. M. Hopkins

Radiation Safety Officer

P.O. Box 80570 Canton, OH 44708

Gentlemen:

Thank you for your report dated July 6, 1990, as supplemented by letter dated July 12, 1990, regarding an iridium-192 source retrieval operation on May 30, 1990. As you reported, no significant problems were encountered during the source retrieval operation. Based on dosimetry (film badge) results and our review of your report, it does not appear that radiation exposures in excess of regulatory requirements were incurred during the retrieval.

We will review this matter further and your corrective actions during a future inspection.

Sincerely.

George M. McCann, Chief Nuclear Materials Safety Section 1

cc: DCD/DCB (RIDS)

00107

RIII (1)
Stavinski/sd
8/14/40

RIII Amm Mallett Bsm

RIII fum McCann dn qu

9009040181 900817 REG3 LIC30 34-25898-01 PD0 IE 07