

APPENDIX A

NOTICE OF VIOLATION

University of Connecticut Health Center
Farmington, Connecticut 06032

Docket No. 030-01295
License No. 06-13022-02

As a result of the inspection conducted on July 18-20, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1988), the following violation was identified:

Condition 23 of License No. 06-13022-02 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in application dated August 7, 1979, and July 25, 1983.

Item 23 of the licensee's application, dated July 25, 1983 states that procedures and precautions for use of radioactive materials are contained in the Radiation Safety Manual on file with the NRC.

Section 3.b., Bioassays, on page 12 of the licensee's Radiation Safety Manual, submitted with the licensee's application dated August 7, 1979, states, in part, that personnel handling iodine-131 in quantities of one or more millicuries for patient treatment will be monitored for thyroid uptake of radioiodine within 3 days.

Contrary to the above as of July 18, 1990, personnel handling 150 millicuries of liquid iodine-131 for patient treatment on July 3, 1990 were not monitored for thyroid uptake of radioiodine.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, University of Connecticut Health Center is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY

ML DL CONNECTICUT - 0003.0.0
08/20/90

9009140115 900829
REG1 LIC30
06-13022-02 PDC

127