Official Record

AUG 2 9 1990

Raleigh General Hospital ATTN: Mr. Kenneth Holt Hospital Administrator 1710 Harper Road Beckley, WV 25801

Gentlemen:

SUBJECT: NRC REPORT NO: 47-18046-01/90-01

Thank you for your response dated June 13, 1990, received by this office on August 22, 1990, to our Notice of Violation, issued on June 28, 1990, concerning activities conducted under NRC Byproduct Material License No. 47-18046-01. We have evaluated your response and found that it meets the requirements of 10 CFR 2.201. We will examine the implementation of your corrective actions during future inspections.

We appreciate your cooperation in this matter.

Sincerely,

ORIGINAL SIGNED

BY

W. E. CLINE

William E. Cline, Chief Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards

cc: State of West Virginia

bcc: Document Control Desk

RII:DRSS CMA SWaldron 847/90 RII:DRSS CHOSEN 847/90

9009140182 900829 REG2 LIC30 47-18046-01 PNU

00103

1/9 IE07 HCA

Post-It" brand fax transmittal	memo 7671 - of pages .
SAWARA WALDOW	Prem AGH
CO. NAC.	Co.
DOGI.	Phono 30 4-05-6- 4/40
Per 304 - 351 - 4449	Bax 904-152 - 4479

June 13, 1990

Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

Reply to a Notice of Violation:

Attachment 10.4, Item 14 of the license application requires that the laboratory be locked when personnel are not present.

The door to the nuclear medicine hot lab was unlocked and open, and personnel were not present in the scanning area. The hot lab is located beside the scanning area within the radiology department, where staff were working. The scanning area and hot lab are also located along a private hallway which is clearly marked private. Our interpretation of Item 14 was that the door to the hot lab would be locked when nuclear medicine personnel were not present in the hospital. The employee on duty at the time of the violation was in the building.

As a corrective action we have made a key available to nuclear medicine staff in a specified location and the door is now closed and locked whenever staff are not within the scanning area. This action was taken on June 13, 1990, and we have been in full compliance since that date.

Thank you,

Diane Eads Keenan, ATR

ne Cals Genan

Technical Director/Radiology

cc: Regional Administrator, Region II Phillip Zsoldos, Assistant Administrator Richard Thompson, Medical Director/Radiology

9007190227 19.

1710 Marper Road Beckley, WV 25801-3397 (304) 256-4100 A Superary of HOA. The Hyalingare Company