


840wm048970E

WM-48




Department of Energy
Albuquerque Operations Office
P.O. Box 5400
Albuquerque, New Mexico 87115

RETURN ORIGINAL TO PDR, HQ.

AUG 10 1990

Mr. Ramon E. Hall
Director, Uranium Recovery
Field Office
Region IV
U.S. Nuclear Regulatory Commission
P.O. Box 25325
Denver, CO 80225



Dear Mr. Hall:

The Nuclear Regulatory Commission (NRC) has expressed concerns regarding the inclusion of three modifications to the Final Remedial Action Plan (RAP) (December 1985) for the cleanup of the Durango, Colorado, Uranium Mill Tailings Remedial Action (UMTRA) site. As you are aware, this document is currently being revised in the new Remedial Action Selection Report format. Accordingly, the substance of each modification derived by application of the supplemental standard provisions of 40 CFR 192 will be summarized in Section 6 of the document, "Radon Attenuation and Site Cleanup," and the actual Department of Energy/NRC authorized RAP Modifications appended. The UMTRA Project Technical Approach Document and NRC Standard Format and Content for Documentation of Remedial Action Selection at Title I Uranium Mill Tailings sites both support this approach.

If you have any questions, please contact Elizabeth Damler of my staff at (505) 845-5654.

Sincerely,

Mark L. Matthews
Project Manager
Uranium Mill Tailings Remedial Action
Project Office

cc:
M. Abrams, UMTRA
D. Gillen, NRC

9010040023 900810
PDR WASTE
WM-48 PDC

DESIGNATED ORIGINAL

Certified By *Mary C. Hood*

Add Info
90-0742