



Commonwealth Edison
1400 Opus Place
Downers Grove, Illinois 60515

October 3, 1990

Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

ATTN: Document Control Desk

Subject: Zion Station Units 1 and 2
Supplemental Response to NRC Bulletin 90-01
NRC Docket No. 50-295/304

References: (a) NRC Bulletin No. 90-01, dated March 9, 1990.
(b) M.H. Richter letter to the NRC dated July 20, 1990

Dear Sir:

NRC Bulletin 90-01 (Bulletin), addressed to all holders of operating licenses or construction permits for nuclear power reactors, requested that addressees promptly identify and take appropriate corrective actions for Model 1153 Series B, Model 1153 Series D, and Model 1154 transmitters manufactured by Rosemount that may be leaking fill-oil.

Reference (b) provided Commonwealth Edison Company's (CECo) response to the Bulletin for Zion Station. Reference (b) indicated that the initial review of plant calibration records was in progress at Zion Station and would be complete by August 31, 1990. This letter provides notification that this review has been completed.

Please address any questions concerning this response to this office.

Respectfully,

D.L. Taylor
Generic Issues Administrator

cc: A.B. Davis, Regional Administrator - RIII
Resident Inspector
C. Patel - Project Manager - NRR

ZNLD/ID237

9010120161 901003
PDR ADDCK 05000295
G PNU

03225

TEB9
1/0