

Appendix A

NOTICE OF DEVIATION

Commonwealth Edison  
Company

Docket No. 50-237  
Docket No. 50-249

Based on the inspection conducted on August 7-10 and 16-18, 1978, it appears that certain of your activities were not conducted in conformance with your commitments to the Commission, as indicated below:

Contrary to the licensee's commitment in Section 7.6.2.5 of the FSAR to provide a liquid radwaste monitoring system capable of showing changes in discharge radiation levels and alarming when the radiation levels approach the limitation for station discharge, in order to provide an additional check on the radiochemistry analyses, the Unit 2/3 liquid radwaste monitor was not capable of detecting radiation levels corresponding to the technical specification discharge limit from January 1978 through the time of this inspection due to excessive internal and external background radiation levels.

LPDR

7810110054

PDR ADOCK 050-010 Q 780908  
PDR ADOCK 050-237 Q 780908  
PDR ADOCK 050-249 Q 780908