



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
801 WARRENVILLE ROAD
LISLE, ILLINOIS 60532-4351

FEB 24 1994

Docket No. 50-341
License No. NPF-43

The Detroit Edison Company
ATTN: D. R. Gipson
Senior Vice President
Nuclear Generation
6400 North Dixie Highway
Newport, MI 48166

Dear Mr. Gipson:

This refers to the routine safety inspection conducted by Messrs. W. J. Kropp, K. Riemer, S. Stasek, and R. Twigg of this office from December 13, 1993, through February 8, 1994. The inspection included a review of activities at your Fermi 2 facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

Although no violations of NRC requirements were identified during the course of this inspection, there were instances where contractor oversight should be improved. In the first case, material supplied by the contractor was found defective during post-installation testing. Further examination determined that the material had not been subject to your receipt inspection process. In the second case, the NRC inspectors found contractor personnel had hung personal clothing on station air system valve handwheels and noted a contract individual sitting on a run of station air system piping. In light of the large number of contractor personnel anticipated necessary to support Fermi's recovery efforts, you are encouraged to ensure appropriate Fermi oversight is provided to preclude contractor related problems during this extended outage.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

08:000

9403090053 940224
PDR ADDCK 05000341
Q PDR

DEO 1/1


FEB 24 1994

The Detroit Edison Company

2

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



M. P. Phillips, Chief
Reactor Projects Section 2B

Enclosures:

Inspection Report
No. 50-341/93028(DRP)

cc w/enclosure:

John A. Tibai, Principal
Compliance Engineer
P. A. Marquardt, Corporate
Legal Department
OC/LFDCB
Resident Inspector, RIII
James R. Padgett, Michigan Public
Service Commission
Michigan Department of
Public Health
Monroe County Office of
Civil Preparedness
Fermi, LPM, NRR
E. G. Greenman, RIII

bcc: "Public"

RIII


Twigg

RIII ^{yes}

Phillips

RIII

Rirok


RIII
2/24/94
Miller

FEB 24 1994


"Public"

The Detroit Edison Company

2

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



M. P. Phillips, Chief
Reactor Projects Section 2B

Enclosures:

Inspection Report
No. 50-341/93028(DRP)

cc w/enclosure:

John A. Tibai, Principal
Compliance Engineer
P. A. Marquardt, Corporate
Legal Department
OC/LFDCB
Resident Inspector, RIII
James R. Padgett, Michigan Public
Service Commission
Michigan Department of
Public Health
Monroe County Office of
Civil Preparedness
Fermi, LPM, NRR
E. G. Greenman, RIII

bcc: "Public"

IE01