



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

MAR 4 1994


License: 11-27355-01
Docket: 030-32210

Wood River Medical Center
ATTN: Alan Stevenson, Administrator
P.O. Box 86
Sun Valley, Idaho 83353

SUBJECT: NRC INSPECTION REPORT 030-32210/93-01

Thank you for your letters of January 4 and February 7, 1994, in response to our letters dated November 17, 1993, and January 18, 1994. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,


Charles L. Cain, Chief
Nuclear Materials Inspection Branch

cc:
Idaho Radiation Control Director

08-088

9403090068 940304
PDR ADOCK 03032210
C PDR

DEPT 11

Wood River Medical Center

-2-

bcc w/copy of licensee's letters:

DMB - Original (IE-07)

LJCallan

SJCollins

LWCamper

MMessier, OC/LFDCB (4503)

WLFisher

CLCain

RABrown

NMIB

MIS System

RIV Files (2)

RIV:NMIB <i>RAB</i>	C:NMIB <i>RAB</i>			
RABrown	CLCain <i>CLCain</i>			
03/1/94	03/3/94			

bcc w/copy of licensee's letters:

DMB - Original (IE-07)

LJCallan

SJCollins

LWCamper

MMessier, OC/LFDCB (4503)

WLFisher

CLCain

RABrown

NMIB

MIS System

RIV Files (2)

RIV:NMIB <i>RAB</i>	C:NMIB <i>RAB</i>			
RABrown	CLCain <i>CLC</i>			
03/1/94	03/3/94			

WOOD
River
MEDICAL CENTER

FEB 15 1994

February 7, 1994

Nuclear Regulatory Commission
Regional Administrator, Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

Attention: Charles L. Cain,
Chief Nuclear Materials Inspection Section V

License No. 11-27355-01
Docket: 030-32210

Subject: Notice of Violation Item 1, NRC
Inspection Report 030-32210/93-01

In response to the Notice of Violation, Item (1), the reason for violation, is as follows:

During the past year there have been changes in several key staff positions associated with our Radiation Safety Program. The changes in personnel involved appointment of individuals who had not previously worked under NRC regulations and guidelines.


These personnel changes contributed directly to all four of the violations cited during the November 2nd inspection.

We currently have in place a Radiology Manager with NRC experience who, along the Radiation Safety Officer are currently reorganizing and reviewing our entire Radiation Safety Program. In addition, training programs are being set up for all key personnel who perform Nuclear Medicine examinations.

If we can be of any further assistance, please feel free to contact: Robert G. Baylor, R.T.R., Radiology Manager or R. Dennis Davis, M.D., Radiation Safety Officer at (208)622-3381.

Thank you.

Sincerely,


R. Dennis Davis, M.D.
Radiation Safety Officer

94-0506 403010260

WOOD
River
MEDICAL CENTER

January 4, 1994

Nuclear Regulatory Commission
Regional Administrator, Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011



Attention: Document Control Desk

Subject: Reply to Notice of Violation
License 11-27355-01
Docket: 030-32210

Response to the violations noted during the 2 November 1993 visit are as follows:

A. 10CFR35.22(b)(6):

The radiation Safety Program is currently being meticulously reviewed by the Radiology Manager and Radiation Safety Officer. We have recently purchased a Nuclear Medicine Procedure Manual as well as a computer program from Biodex to help maintain proper documentation. When complete, the program will be reviewed by the Radiation Safety Committee members.

B. 10CFR35.60(b):

Labels have been procured (see Attachment #1) for conspicuous labeling of all radiopharmaceuticals used by this department. In addition, the patients last name and first initial are noted on the label.

C. 10CFR35.39(b)(2):

Roger Stano, our Radiation Specialist, has been contacted to come up to visit our facility. During his visit he will demonstrate the proper procedure and documentation required to conduct sealed source tests. After this training, we will implement into our Nuclear Medicine Policy the requirement that a sealed source test be accomplished at least quarterly. Roger Stano is slated to arrive at our facility either in late January or early February.

94-0387

9401140225

Nuclear Regulatory Commission
RE: License No. 11-27355
January 4, 1994
Page Two


D. 10CFR35.30(e) and 35.50(e)(3):

We have implemented a new policy whereby at each Radiation Safety Committee meeting the Radiation Safety Officer will ensure the records for the quarterly linearity tests of the dose calibrator and sealed source test have been reviewed and signed.

Full compliance of the above-mentioned violations will be achieved no later than 1 March 1994. This time frame is in sync with our quarterly Radiation Safety Committee meeting.

If we can be of any further assistance please feel free to contact: Robert G. Baylor, R.T.R., Radiology Manager or R. Dennis Davis, M.D., Radiation Safety Officer, at (208)622-3381.

Thank you.



Robert G. Baylor, R.T.R.
Radiology Manager

Tc 04

----- Tc99m

Tc MAA

----- Pulmolite

Tc AC

----- Microlite

Tc MDP

----- Osteolite

Tc HIDA

----- Hepatolite

----- DTPA

----- Pyrolite

Tc RBC

----- Tc Labelled Red Blood Cells