

Appendix

NOTICE OF VIOLATION

State of Michigan

License No. 21-05199-03  
License No. SNM-1385

As a result of the inspection conducted on December 9, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

License No. 21-05199-03

1. License Condition No. 19 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in application received March 26, 1979 and referenced letters.

Item No. 11 of the application required quarterly calibration of your survey instruments.

Contrary to the above, quarterly calibrations of your survey instruments were not performed. Specifically, the Eberline E-120E survey instrument, serial no. 7731, was last calibrated in January 1982, and the Eberline E-120E survey instrument, serial no. 7960 has not been calibrated since receipt in 1981. These are periods greater than the three months requirement.

This is a Severity Level IV violation (Supplement VI).

License No. SUB-1385

2. 10 CFR 20.203(e)(2) requires that areas in which specified amounts of natural uranium are used or stored by conspicuously posted with a sign bearing the radiation caution symbol and the words "Caution - Radioactive Material".

Contrary to the above, on the day of the inspection, the barn storage area containing natural uranium bearing ceramic tiles was not properly posted.

This is a Severity Level IV violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

\_\_\_\_\_  
Dated

\_\_\_\_\_  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2