

APPENDIX A

NOTICE OF VIOLATION

Carolina Power and Light Co.
Shearon Harris

Docket Nos. 50-400
License Nos. CPPR-158

As a result of the inspection conducted on September 14-17, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion III, as implemented by Carolina Power and Light Corporate QA Manual Section 3 requires that design changes including field changes shall be subject to design control measures commensurate with those applied to the original design and be approved by the organization that performed the original design.

Contrary to the above, process control cabinets SA-09, SA-13, SB-10 and SB-14 were installed per FCR-M-462 without verifying that the mounting design specified in the FCR met the original seismic qualification test requirements that were performed on the equipment by the vendor.

This is a Severity Level V Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: October 4, 1982