

Independent Testing Laboratories

Post Office Box 219257, Houston, Texas 77218-9257, (713) 579-0561

February 8, 1994

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

Subject:

Reply to a Notice of Violation

In reference to your inspection report 150-00042/93-01 regarding the inspection conducted by Mr. Robert A. Brown on December 14, 1993, in Watertown, South Dakota, it was found that our personnel did not have proper shipping papers for the Iridium 192 source which was being used at this jobsite. It was our understanding that our daily survey log contained sufficient information to comply with the appropriate Department of Transportation (DOT) regulation.

Since your January 3, 1994, telephone conversation with Mr. Homer Wilson, VP of Operations for our company, a form was prepared. We have enclosed this form for your review.

This form has been distributed to all personnel of Independent Testing Laboratories (ITL) on or before January 17, 1994. Therefore, based on this telephone conversation, we feel this form will bring ITL into full compliance with all appropriate regulations.

If you have any questions or need additional information, please don't hesitate to contact us at 1-800-643-8136.

Sincerely yours,

Walter C. Crager Radiation Safety Officer

cjb/57ADM1

030057

cc:

J. W. Lawson, Sr.

U.S. NRC, Regional IV Administrator

A DIVERSIFIED INSPECTIONS COMPANY

FACSIMILE: (713) 579-6464

9403100205 940208 PDR STPRG ESGSD PDR (800) 643-8136



BILL OF LADING RADIOACTIVE MATERIAL

1	1 Model 650 Shipping Container		
Radi UN2	oactive Material, special 974	form NOS	
Radi	oactive Yellowsportation Index	GBq Total*	
USA/6717/B(U) type B Emergency Response No. (713) 427-1138.			
Radi	iographer(s)		
	og.upaci(s)		
Date			
Radi	iation Safety Officer		
Date			
Date			

* GBq = no. of curies x .037

1ADM1266

A DIVERSIFIED INSPECTIONS COMPANY

FACSIMILE: (713) 579-6464