Appendix

NOTICE OF VIOLATION

Twin City Testing and Engineering Laboratory, Incorporated

License No. 22-01376-03

As a result of the inspection conducted on December 13 and 15, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 13 requires that your chromatograph detectors containing nickel-63 be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, you failed to test your chromatograph dectectors containing nickel-63 for contamination or leakage from July 19, 1981, to November 22, 1981, a period exceeding six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated 23/83

D. G. Wiedeman, Chief Materials Radiation Protection

Section 1