


TEXAS UTILITIES GENERATING COMPANY

2001 BRYAN TOWER DALLAS, TEXAS 75201-3050



R. J. GARY
EXECUTIVE VICE PRESIDENT
AND GENERAL MANAGER

December 27, 1982
TXX-3604

Mr. G. L. Madsen, Chief
Reactor Project Branch 1
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Docket Nos.: 50-445
50-446

COMANCHE PEAK STEAM ELECTRIC STATION
PIPE WHIP RESTRAINT WELD INDICATIONS
SDAR-95; CP-82-12
FILE NO.: 10110

Dear Mr. Madsen:

On September 30, 1982, we verbally informed your Mr. R. G. Taylor of a deficiency regarding weld indications in certain pipe whip restraints. We submitted an interim report logged TXX-3584 on October 25, 1982.

We have completed our investigation and concluded that the matter is not reportable under 10 CFR50.55(e). Records supporting this determination are available for your Inspector's review at the CPSES site.

Very truly yours,

R. J. Gary
R. J. Gary

RJG:eaq

cc: NRC REGION IV - (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, DC 20555

8301040545 821227
PDR ADOCK 05000445
S PDR

1827