

APPENDIX A

NOTICE OF VIOLATION

Carolina Power and Light Co.
H. B. Robinson

Docket No. 50-261
License No. DPR-23

As a result of the inspection conducted on September 23-24, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion V, and the accepted QA Program (March 18, 1982 letter, serial number OQA-81-026) require that activities affecting quality be prescribed by documented instructions of a type appropriate to the circumstances and be accomplished in accordance with these instructions.

Contrary to the above, instructions issued to implement IE Bulletin 80-11 requirements were not adequate to assure that all masonry walls in the vicinity of safety-related equipment would be identified and re-evaluated for their conformance to design requirements.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: October 29, 1982