



Public Service Company of Colorado

P. O. Box 361, Platteville, Colorado 80651

October 27, 1978
Fort St. Vrain
Unit No. 1
P-78176

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

REF: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/78-32/03-L-0, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)1, AC 7.5.2(b)2, and AC 7.5.2(b)3.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/78-32/03-L-0, Final.

Very truly yours,

Don Warembourg
Don Warembourg
Nuclear Production Manager

DW/alk

cc: Director, Office of Management Information
and Program Control

781031 0225 S

D002
S11