

APPENDIX A

SEP 15 1978

NOTICE OF VIOLATION

Duke Power Company

License No. SNM-1773

Based on the results of the NRC inspection conducted on August 1-6, 1978, it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in our correspondence to you dated December 31, 1974.

Section 9 of NRC Materials License No. 1773 authorizes the storage of fuel, "in accordance with statements, representations and conditions specified in the licensee's application dated June 1, 1977, and supplements thereto dated October 6 and 24, 1977, and subject to the hereinafter listed conditions."

The licensee application dated June 1, 1977, specifies that administrative controls have been implemented to preclude the use of hydrogenous firefighting materials in the New Fuel Storage Vault and the Spent Fuel Storage Pool and that dry chemical or CO₂ type fire extinguishers will be provided in these areas.

Contrary to these requirements, administrative controls had not been established to preclude the use of hydrogenous firefighting materials in the New Fuel Storage Vault or the Spent Fuel Storage and no dry chemical or CO₂ fire extinguishers were observed in these areas on August 2, 1978.

7810310312