

APPENDIX A

IE HQ FILE COPY

NOTICE OF VIOLATION

Public Service Electric and Gas Company
Hope Creek Generating Station, Unit 1

Docket No. 50-354
License No. CPPR-120

During inspection on November 1 - December 5, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2 Appendix C) published in the Federal Register on March 9, 1982 (47 FR 9987), the following violation was identified:

10 CFR 50, Appendix B, Criterion X states that inspection of activities affecting quality shall be executed to verify conformance with the governing documents. This is implemented by paragraph 4.1.2.1 of PSE&G Quality Assurance Instruction 10-1 which states that Bechtel must provide inspection of work done by their own departments.

Paragraph 7.1.1 of Section III of the Bechtel Construction Quality Control Manual states that construction installation activities including modifications and repair are to be inspected to assure conformance with program criteria.

Bechtel QCI P-2.10, which specifies inspection requirements for initial installation of pipe supports and restraints, states that its purpose is to assure that support and restraint installation is performed in accordance with the requirements of the design documents.

Contrary to the above, as of November 9, 1982, an NRC inspection of initial installation of pipe supports and restraints performed after inspection by Bechtel QC to QCI P-2.10, identified four installations not in accordance with the requirements of the design documents.

This is a Severity Level IV Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Public Service Electric and Gas Company is hereby required to submit to this office within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

8301040592 821220
PDR ADOCK 05000354
G PDR

OFFICE ▶							
SURNAME ▶							
DATE ▶							