

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

SEP 1 5 1978

Docket No. 50-346

Toledo Edison Company ATTN: Mr. W. A. Johnson Senior Vice President Operations Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This letter refers to the inspection conducted at Davis-Besse Nuclear Power Station, Unit 1 by Messrs. T. Tambling, J. Foster, J. Menning and J. Streeter of our Region III office in Glen Ellyn, Illinois, on June 6-8, 13-15, 20-23, and July 17-19, 1978. The inspection was performed to review the reportable occurrence on June 2, 1978, involving discovery of the design and installation defects associated with the Safety Feature Actuation System sequencer logic. The findings from this inspection were reviewed with Mr. T. Murray, Plant Superintendent, and others of your staff on June 8, 15, 23, and July 19, 1978 and with you and others on August 16, 1978.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

A separate letter setting forth certain matters of concern and the items of noncompliance found during this inspection has been sent from the Director, Division of Reactor Operations Inspection, Office of Inspection and Enforcement. Your response to those items should be made directly to that office.

7811030306

Toledo Edison Company - 2 - SEP 1 5 1978

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

64

٠.

James G. Keppler Director

Enclosure: 1E Inspection Rpt No. 50-346/78-19

. . .

. .

2

1.

cc w/encl: Mr. J. Williamson, President and Chief Executive T. Murray, Station Superintendent Central Files Reproduction Unit NRC 20b PDR Local PDR NSIC TIC U. Young Park, Power Siting Commission