

APPENDIX A

NOTICE OF VIOLATION

Consolidated Edison Company
of New York, Inc.
4 Irving Place
New York, New York 10003

Docket No. 50-247

License No. DPR-26

Indian Point Station - Unit 2

As a result of an inspection conducted on July 26 - 30, 1982, and in accordance with the Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

10 CFR 71.53(c) states "Packaging shall be conspicuously and durably marked with its model number. Prior to applying the model number, the licensee shall determine that the packaging has been fabricated in accordance with the design approved by the Commission."

Contrary to the above, on July 23, 1982, the licensee used package Model No. CNS 14-195H for the shipment of 13,432 Curies of licensed material, and did not determine that the package had been fabricated in accordance with the design approved by the Commission.

This is a Severity Level V violation (Supplement V).

OFFICIAL RECORD COPY