

DEC 17 1982

APPENDIX A  
NOTICE OF VIOLATION

Exton Materials, Inc.  
Malvern, Pennsylvania 19355

Docket No. 30-17537  
License No. 37-19394-01

As a result of the inspection conducted on November 23, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

Condition 14.A of License No. 37-19394-01 requires that sealed sources containing licensed material be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, as of November 23, 1982, sealed sources containing 10 millicuries of cesium-137 and 40 millicuries of americium-241 had not been tested for contamination or leakage since purchase in April 1981, an interval of more than six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Exton Materials, Inc. is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

Dated DEC 17 1982

OFFICIAL RECORD COPY

8301040714 821217  
NMS LIC30  
37-19394-01 PDR