

APPENDIX A

NOTICE OF VIOLATION

Jersey Central Power and Light Company

Docket No. 50-219

Based upon the results of the NRC inspection conducted at the Oyster Creek Station on August 22-24, 1978, it appears that one of your activities was not conducted in accordance with the conditions of your facility operating license, DPR-16, as described below. This item is an Infraction.

Oyster Creek Station Technical Specification 6.11 requires that procedures for personnel radiation protection be prepared and adhered to. Health Physics Procedure 906.17, Spike Testing and Leak Testing of Self-Reading Dosimeters, prepared pursuant to Technical Specification 6.11 requires that self-reading dosimeters be spike and leak tested prior to being placed into service and every 6 months thereafter.

Contrary to the above, self-reading dosimeters in the various emergency kits at the time of the inspection, had been placed into service without prior spike and leak testing.

7811080264