

APPENDIX A  
NOTICE OF VIOLATION

Carolina Power & Light  
H. B. Robinson 2

Docket No. 50-261  
License No. DPR-23

As a result of the inspection conducted on September 10 - October 11, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.13.1a requires that any individual entering a high radiation area shall be provided with a radiation monitoring device which continuously indicates the radiation dose rate in the area.

Contrary to the above, on October 5, 1982, a mechanic was observed exiting from the high radiation areas associated with the spent fuel cask washdown area and auxiliary building sump without a radiation dose rate meter.

This is a Severity Level V Violation (Supplement IV.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: OCT 25 1982