

Appendix

NOTICE OF VIOLATION

Decatur Memorial Hospital

License No. 12-03332-02

As a result of the inspection conducted on December 9, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 20 requires that you test your sealed sources containing byproduct material for leakage and/or contamination at intervals not to exceed six months. In the absence of a certificate from a transferor indicating that a test has been made within six months prior to the transfer, a sealed source received from another person shall not be put into use until tested.


Contrary to the above, it was learned from statements of licensee representatives and a review of records that this requirement was not met. Specifically, your barium-133 sealed source purchased in March 1982, was leak tested on September 21, 1981, as evidenced by a leak test certificate that accompanied the source, and you failed to perform a leak test of that source until June 1, 1982, a period greater than six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

12/23/82



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1