

40-6659

# Petrotomics Company

P.O. Box 8509, Shirley Basin, Wyoming 82615 Telephone: (307) 234-9341

February 28, 1994

Branch Chief  
Uranium Recovery Branch  
Division of Low-Level Waste Management  
and Decommissioning, NMSS (5 E2)  
U. S. Nuclear Regulatory Commission  
11555 Rockville Pike  
Rockville, MD 20850

Reference: License Condition No. 23  
Source Materials License SUA-551

Dear Sir:

License Condition No. 23 requires that the annual update to the surety amount be submitted at least three months prior to the June 1 anniversary date, or by March 1, 1994. No changes have been made to the current approved reclamation plan, or corrective action plan, and there has been no additional land disturbance. We propose to update the surety amount by adjustment for inflation from December 1992 to December 1993, based on the increase in the Consumer Price Index (a factor of 1.0275). The surety amount would increase by \$142,377 to a total of \$5,319,724.

Please contact us if you have questions or need additional information.

Sincerely,

*R. A. Juday*  
R. A. Juday  
Supervisor

pc: Director  
Division of Radiation Safety  
and Safeguards, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

Mr. Ramon Hall  
Director  
U.S. Nuclear Regulatory Commission  
Uranium Recovery Field Office  
Region IV  
P. O. Box 25325  
Denver, CO 80225

9403140120 940228  
PDR ADDCK 04006659  
E PDR

090150

COIT# P 726 452 078

NK10 1/0