

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

November 24, 1978

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BFRO-50-260/7819

The enclosed report provides details concerning main steam line radiation
monitors RM-90-135, -136, -137, and -138 which were found less conservative
during normal operation than allowed by technical specification 3.1.A
(table 3.1.A). This report is submitted in accordance with Browns Ferry
unit 2 technical specification 6.7.2.a(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

A002
5/11

78112802015

An Equal Opportunity Employer