

ENCLOSURE

NOTICE OF VIOLATION

Diagnostic Photon Corporation  
Carolina, Puerto Rico

Docket No. 030-19134  
License No. 52-16345-02MD

During an NRC inspection conducted January 26, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

License Condition 12 requires, in part, that records of leak test results be kept in units of microcuries.

Contrary to the above, leak tests performed between December 29, 1992 and January 26, 1994, were not kept in units of microcuries. Specifically, no defining units were used.

This is a repeat Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Diagnostic Photon Corporation is hereby required to submit a written statement or explanation to the Regional Administrator, Region II, with a copy to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or demand for information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia  
This 23<sup>rd</sup> day of February, 1994

9403150243 940223  
PDR ADOCK 03019134  
C PDR