

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

December 22, 1982

HAL B. TUCKER

VICE PRESIDENT

NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

Mr. J. P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Catawba Nuclear Station
Unit 2
Docket No. 50-414

Dear Mr. O'Reilly:

In accordance with 10CFR 50.55e Significant Deficiency Report SD 414/82-25 was to be submitted by this date. During the course of the investigation of extensive lack of penetration on the roots of several Class C welds, made by the same welder, additional concerns were uncovered. A full evaluation will be provided by January 31, 1983.

Very truly yours,

H B Tucker

Hal B. Tucker

RWO:scs

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. P. K. Van Doorn
NRC Resident Inspector
Catawba Nuclear Station

Mr. Robert Guild, Esq.
Attorney-at-Law
314 Pall Mall
Columbia, South Carolina 29201

Palmetto Alliance
2135 1/2 Devine Street
Columbia, South Carolina 29205

8301060350 821222
PDR ADOCK 05000414
S PDR

OFFICIAL COPY

LE 27