

APPENDIX A

NOTICE OF VIOLATION

Alabama Power Company

License No. NPF-2

Based on the results of the NRC inspection conducted on September 12-14, 1978, it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in our correspondence to you dated December 31, 1974.

Technical Specification 3.8.1.1 requires that two separate and independent diesel generator sets (one 4075 KW and one 2850 KW) be operable in Modes 1, 2, 3 and 4.

Contrary to the above, on September 14, 1978, the inspector observed that the starting air receivers for the 1B (4075 KW) diesel were insufficiently pressurized to insure starting of the diesel.

This is an infraction.

7812050015