

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011 8064

MAR 1 0 1994

License: 15-23181-01 Docket: 030-28681

Alpha-Omega Geotech, Inc. ATTN: Roy Leonard, President P.O. Box 2670 Kansas City, Kansas 66110

SUBJECT: NRC INSPECTION REPORT 030-28681/93-01

Thank you for your letter of February 22, 1994, in response to our letter and Notice of Violation dated January 24, 1994. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

Chadee I. Caim

Charles L. Cain, Chief Nuclear Materials Inspection Branch

cc: Kansas Radiation Control Program Director

9403160072 940310 PDR ADOCK 03028681 C PDR JE07 1

bcc w/copy of licensee letter:
DMB - Original (IE-07)
LJCallan
SJCollins
RAScarano, DRSS/RIV
LWCamper
MMessier, OC/LFDCB (4503)
WLFisher
CLCain
RALeonardi
NMIB
MIS System
RIV Files (2)

RIV: NMIB RaZ	C:NMIB(LC	
RALeonardi	CLCain	
03/09/94	03/9/94	

bcc w/copy of licensee letter:
DMB - Original (IE-07)
LJCallan
SJCollins
RAScarano, DRSS/RIV
LWCamper
MMessier, OC/LFDCB (4503)
WLFisher
CLCain
RALeonardi
NMIB
MIS System
RIV Files (2)

RIV: NMIB ROZ	C:NMIBULC	
RALeonardi	CLCain	
03/09/94	03/9/94	

February 22, 1994



GEOTECHNICAL SERVICES: DESIGN . CONSTRUCTION . FORENSIC

3 28

U. S. Nuclear Regulatory Commission Attn. Document Control Desk Washington, D. C. 20555

FAX: 301-504-2080

Reply to Notice of Violation, Docket #030-28681, License #15-23181-01

This letter is in response to the above-referenced notice of violation. We were given this violation for a failure to maintain a maximum interval of 6 months between sealed source leak tests. We have corrected this by adopting two designated one-month intervals, June and December, in the calendar year, in which all of our gauges will be leak tested. This corrective action will be begun and documented in June, 1994. We are now in compliance with the six-month, maximum, interval.

Frank Comer

Construction Services Manager, RSO

Trank Come

cc: Regional Administrator, Region IV, 61! Ryan Plaza Drive, Suite 400, Arlington, TX 76011 Fax. No. 817-860-8210

H-0569

9403040071