

APPENDIX A

NOTICE OF VIOLATION

Northeast Nuclear Energy Company

Docket No. 50-245

Based on the results of an NRC inspection conducted on October 3-6, 1978, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC license as indicated below. This item is an Infraction.

Technical Specification 6.8.1 states in part: "Written procedures shall be established, implemented and maintained covering . . . surveillance activities of safety-related equipment."

Surveillance Procedure 6.6.8.1, Operational Readiness Demonstration (Diesel Generator), requires that during surveillance testing the diesel generator be operated at full load as required by Technical Specification 4.9.A.1.a.

Contrary to the above, data reviewed for ten surveillances performed June 13, 1978, through August 14, 1978, showed that the engine appeared not to have been operated at full load during the performance of the surveillances. The engine appeared to have been operated at approximately 60% load.

7812110305