## LICENSEE EVENT REPORT

	CONTPOL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	M I D C C 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
0 1 7 8	SOURCE L 6 0 5 0 0 5 3 1 6 7 1 2 0 4 8 2 8 0 1 0 8 8 3 9
0 2	FOLLOWING SLUDGE LANCING ON STEAM GENERATOR #21, THE SLUDGE LANCE
0 3	LINES WERE FOUND CONNECTED TO THE EAST BLOWDOWN DEMINERALIZER IN A
0 4	CONFIGURATION WHICH BYPASSED RMS CHANNEL DRA-353. THIS RESULTED IN
0 5	[AN UNMONITORED RELEASE OF APPROXIMATELY 200 GALLONS. A SAMPLE OF THE]
0 6	WATER WAS OBTAINED AND ANALYZED WHICH REVEALED THAT A CALCULATED
0 7	TOTAL OF 3.499E-6 CURIES HAD BEEN RELEASED.
0 8	9 80
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
	17 REPORT NUMBER 8 2 - 10 5 0 4 L - 0
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER  H 18 Z 19 1 Z 20 Z 2 2 3 30 31 32  COMPONENT MANUFACTURER  H 18 Z 19 1 2 20 Z 20 Z 20 36 37 40 41 23 42 43 25 Z 9 9 9 9 26
1 0	THE RESPONSIBLE SUPERVISOR HAD MISUNDERSTOOD THE INSTRUCTIONS
1 1	OUTLINING THE LOCATIONS AVAILABLE FOR CONNECTING THE SLUDGE LANCE
12	LINES. THE SUPERVISOR HAS REVIEWED THE EVENT AND IS AWARE OF ALL
13	PERTINENT ASPECTS. FUTURE SLUDGE LANCE PROCEDURES WILL HAVE STEP
1 4	SPECIFING CONNECTIONS FOR SLUDGE LANCE LINES.
1 5	ACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPT
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35  LEASED OF RELEASE AMOUNT OF ACTIVITY 35  LOCATION OF RELEASE 36  TURBINE ROOM SUMP  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY 35  TURBINE ROOM SUMP  45
1 7	NUMBER TYPE DESCRIPTION (39)  O O O O O Z Z 38 N/A  PERSONNEL INJURIES 13
1 1	NUMBER DESCRIPTION(41) 0 0 0 40 N/A
	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  Z 42 N/A
2 0	PUBLICITY (45) PDR ADOCK 05000316 NRC USE ONLY PDR (50000316) NRC USE ONLY PDR (500000316) NRC USE ONLY PDR (500000316) NRC USE ONLY PDR (5000000000000000000000000000000000000
/ 4	NAME OF PREPARER T.P. BEILMAN PHONE 616/465/5901