

NOV 22 1978

APPENDIX A

NOTICE OF VIOLATION

Alabama Power Company

License Nos.: NPF-2
DPFR-86

Based on the results of the NRC inspection conducted on October 4-7, 1978, it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in our correspondence to you dated December 31, 1974.

Technical Specification 6.8.1 requires written procedures be established, implemented, and maintained covering procedures recommended in Appendix A of Regulatory Guide 1.33. Regulatory Guide 1.33, Appendix A, Section J, requires procedures covering calibration of analytical equipment. Procedure FNP-O-CCP-3, "Determination of Chloride Ion in Water," Section 7.2 requires calibrations using standard solutions.

Contrary to the above, on October 5, 1978, no calibrations or periodic recalibrations had been conducted as per Section 7.2 of FNP-O-CCP-3 in reactor coolant chloride chemistry analysis.

This item is a deficiency.

781214 0119