

MOUNT SINAI MEDICAL CENTER

DANIEL A. KANE
President

December 13, 1982

Mr. D. G. Wiedeman, Chief
Materials Radiation Protection, Section 1
U. S. Nuclear Regulatory Commission, Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Re: License No. 48-03280-01

Dear Mr. Wiedeman:

This is in response to your letter dated November 29, 1982, pursuant to the provisions of 10CFR2.201.

As a result of the inspection conducted at Mount Sinai Medical Center on November 10, 1982, the following violations were identified:

1. The Nuclear Medicine dose calibrator was not tested for linearity during second quarter 1981 nor first quarter 1982; and the Nuclear Cardiology dose calibrator was not tested during fourth quarter 1980 nor first quarter 1982.
2. The gold-195 and two cesium-137 check sources and an americium-241 anatomical marker were leak tested annually, rather than at an interval not to exceed six months.

The corrective action to be taken to avoid further noncompliance will be that the Radiation Safety Officer or his designee will verify testing and the results thereof within the time frames required by regulation or license condition. The date full compliance was achieved was at the time of the inspection.

If you have additional questions regarding this correspondence, please contact Dr. Charles Wilson at 414-257-5381.

Sincerely,



Daniel A. Kane

8301170324 830111
NMS LIC30
48-03280-01 PDR

cc: Charles Wilson, Ph.D.

950 North Twelfth Street, P.O. Box 342 • Milwaukee, Wisconsin 53201 • 414/289-8001

Affiliated with

The University of Wisconsin Medical School • The Medical College of Wisconsin • Marquette University School of Dentistry

DEC 17 1982