DC010cb

Docket Nos. 50-254; 50-265 License Nos. DPR-29; DPR-30

Commonwealth Edison Company ATTN: Mr. R. Pleniewicz Site Vice President Quad Cities Station 22712 206th Avenue North Cordova, IL 61242

Dear Mr. Pleniewicz:

This refers to the special safety inspection conducted by D. Shepard and F. Brush of this office and C. Goodman of NRR on February 3 and 4, 1994. This inspection included a review of authorized activities for your Quad Cities Nuclear Power Station, Units 1 and 2 facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

The inspectors reviewed the event time line and management efforts to determine the root cause of the rod mispositioning event which occurred January 27, 1994, on Unit 2. This event was assigned a Level II multi-disciplinary investigative team by your staff. The investigative team's effort was not yet complete at the carrius on of this special inspection and is not discussed in this report.

Although the safety significance of this event was small, this event further demonstrates a longstanding problem of personnel errors at Quad Cities for which your past efforts to improve overall plant performance have been ineffective. In addition, management oversight provided to personnel filling the new position of unit supervisor appeared minimal. That lack of oversight may have contributed to the event. The recent plant management changes at Quad Cities affords an opportunity to perform an effective root causes investigation and develop effective corrective actions. We request a copy of your investigation team's final report.

The inspectors reviewed selective procedures and representative records, interviewed licensee personnel, and observed activities in progress.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

华川

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Edward G. Greenman, Director Division of Reactor Projects

Enclosure:

1. Inspection Report

No. 50-254/94003(DRP) No. 50-265/94003(DRP)

cc w/enclosure:

L. O. DelGeorge, Vice President,

Nuclear Oversight & Regulatory Services

G. Campbell, Station Manager

N. Chrissotimos, Regulatory Assurance

Supervisor

D. Farrar, Nuclear Regulatory

Services Manager

OC/LFDCB

Resident Inspectors, Quad Cities,

Dresden, LaSalle, Clinton

R. Hubbard

J. W. McCaffrey, Chief, Public

Utilities Division

Licensing Project Manager, NRR

State Liaison Officer

Chairman, Illinois Commerce

Commission

J. B. Martin, RIII

H. J. Miller, RIII

T. O. Martin, RIII

See Previous Concurrences

RIII

RIII

RIII

RIII

RIII EN RIII

Shepard

Hiland

Clayton

Ring

Hausman

Greenman

We will giadly discuss any questions you have concerning this inspection.

Sincerely,

Edward G. Greenman, Director Division of Reactor Projects

Enclosure:

1. Inspection Report
No. 50-254/94003(DRP)
No. 50-265/94003(DRP)

cc w/enclosure:

L. O. DelGeorge, Vice President, Nuclear Oversight & Regulatory Services

G. Campbell, Station Manager

N. Chrissotimos, Regulatory Assurance Supervisor

D. Farrar, Nuclear Regulatory Services Manager

OC/LFDCB

Resident Inspectors, Quad Cities, Dresden, LaSalle, Clinton

R. Hubbard

J. W. McCaffrey, Chief, Public Utilities Division

Licensing Project Manager, NRR

State Liaison Officer

Chairman, Illinois Commerce Commission

J. B. Martin, RIII

H. J. Miller, RIII

T. O. Martin, RIII

Ves

RIII PALT Shepard Hiland

Clayton 3/6/94

RIII Ring RIII

Hausman

RIII

Greenman