10 CFR 2 201	SAFETY	INSPECTION	Page 1 of 1			
Testmaster Inspection Company, Inc. P.O. Box 31 Perrysbury, OH 43552		2. REGIONAL OFFICE  REGION III  U S NIJCLEAR REGULATORY COMMISSION  799 ROOSEVELT ROAD  GLEN ELLYN II. 60137				
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S	5)	5. DATE OF INSPECTION			
030-29789	34-24872-01		February 25, 1994			
Regulatory Commission (NRC) rules and regu	lations and the condition	is of your license. The in	to radiation safety and to compliance with the Nuclea spection consisted of selective examinations of ector. The findings as a result of this inspection are a			
Within the scope of this inspection,	no violations were observ	ved				
The inspector also verified the steps questions on those actions at this time.		of the violations identified	during the last inspection. We have no further			
X 3. Ouring this inspection certain of you NOTICE OF VIOLATION, which is re	ur activities, as described quired to be posted in ac	below or attached, were coordance with 10 CFR 19	in violation of NRC requirements. This form is a 9.11.			
			was not properly posted to			
indicate the presence of a			. 10 CFR 20.203(b),(c),(d),(e) or 34.42.			
В.	of sealed sources were not					
performed at the proper freq	uencies. 10 CFR	or Licens	e Condition Number			
C. Records of			were not properly maintained.			
10 CFR	or License Condition	Number				
D. Documents were not properly	y posted or otherwise ma	ade available. 10 CFR 19	.11.			
	Reports or notification ofwere not made in accordance with					
10 CFR			able to authorities in the event			
y F. Failure to have	inspection 10	CFR 71.5. refe	rencing 49 CFR 177.817(e).			
of accidenc of	mspeceron: 10	2777 74.04				
I hereby state that, within 30 days, the action above. This statement of corrective actions unless required by the NRC.	ns described by me to the	e Inspector will be taken that the requirements of 10	to correct the violations identified in the items checked 0 CFR 2.201. No further response will be submitted			
SIGNATURE - LICENSEE 9403220069 940303 PDR ADOCK 03029789 C PDR	DATE	SIGNATURE - NBC II	Mula 3/2/94			

O (TEO) PUBLIC

NRG FORM 591 PART 1 (7-91)

## SAFETY INSPECTION

U.S. NUCLEAR REGULATORY COMMISSION

N 64 5.201				Page 1 of		
1 UCENSEE  Testmaster Inspection Company, Inc. P.O. Box 31 Perrysbury, OH 43562		2. REGIONAL OFFICE  REGION III  U.S. NUCLEAR REGULATORY COMMISSION  799 ROOSEVELT ROAD  GLEN ELLYN IL. 60137				
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S		5. DATE OF INSPECTION			
			February 25, 1994			
LICENSEE: The inspection was an examination of the act Regulatory Commission (NEC) rules and regulatory commission (NEC) rules and regulatory follows:	lations and the condition	is of your license. The ins	pection consisted of selective e	xaminations of		
1. Within the scope of this inspection,	no violations were observ	red				
The inspector also verified the steps questions on those actions at this till.		of the violations identified	during the last inspection. We	have no further		
During this inspection certain of you NOTICE OF VIOLATION, which is re				This form is a		
A			was not properly (	posted to		
indicate the presence of a	10 CFR 20.203(b),(c),(d),(e) or 34.42					
8.	of sealed sources were not					
parformed at the proper frequ	iencies. 10 CFR	or License	Condition Number			
C. Records of	were not properly maintained.					
10 CFR	_ or License Condition N	Number				
D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.						
E. Reports or notification of			were not made in	accordance with		
10 CFR	or License Condition h	Number				
F. Failure to have shipping papers readily available to authorities in the event						
			encing 49 CFR 177,61	7(e).		
219053						
Lo L V V V						
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.						
SIGNATURE - LICENSEE	DATE	SIGNATURE - NEC INS	PECTOR	DATE		
All Ill Some	0 100	-	Mala	3/2/94		
NRC FORM 591 Part ) (7-91)	The second	ratio sakaranan efisioners	Bah 1 I			