Carneton February 8, 1994 MPI Pharmacy Services, Inc. U.S. Nuclear Regulatory Commission 344A Gest Street Region III Cincinnati, OH 45203 801 Warrenville Rd. Lisle, IL 60532 rel (\$13) 241-5955 fax (513) 241-2335 Attn: B.J. Holt, Chief Nuclear Materials Inspection Section 1 mersham RE: License No: 34-26239-01MD Docket No: 030-31889 Dear Ms. Holt, This refers to the routine safety inspection conducted by James L. Cameron on December 11, 1993. REPLY TO MOTICE OF VIOLATION A violation was cited for failure to perform routine thyroid monitoring. Each of the two individuals were on vacation when the bioassay came due. To correct this problem the RSO or his alternate will check the staff vacation schedule in advance of thyroid monitoring and reschedule monitoring when a conflict occurs. A violation was cited for failure to perform air effluent monitoring on a timely basis. The facility RSO or his alternate will ensure air effluent monitoring is performed on a timely basis. A trained employee will be assigned the task prior to the due date. The RSO will then follow up to be sure air effluent monitoring has been performed in a timely fashion. ADDITIONAL INFORMATION The inspector's recommendation of semiannual facility RSO audits is appreciated and will be implemented. These audits will be reviewed by the facility manager for completeness and adherence to this facility's Nuclear Regulatory Commission license conditions. The inspector expressed concern about the plexiglass over the detectors of the package survey station. The possibility of an error in measurement leading to a package labeling mistake has been addressed by cutting holes in the plexiglass. This should minimize any possible attenuation of the radiation. 9403220109 940315 PDR ADOCK 03031889 FEB 1 4 1994

If there are any further questions, please do not hesitate to contact me at the above address or phone number.

Sincerely,

James Dawson, RPh. Radiation Safety Officer