



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 23, 1980

D. L. ASWELL
Vice President-Power Production

LPL 15163
Q-3-A35.07.06
Q-3-A35.07.10
Q-3-A35.02.01

S

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Final Report of Significant Construction
Deficiencies No. 6 and No. 10
No. 6 - "Emergency Diesel Generators - Defective Shafts & Springs"
No. 10 - "Defective Emergency Diesel Generator Roller Pins"

REFERENCE: LP&L Letter, LPL 10343 dated December 29, 1978
LP&L Letter, LPL 10233 dated December 5, 1978
As amended by LPL 10316 dated December 19, 1978
As amended by LPL 11903 dated August 31, 1979
As amended by LPL 12319 dated October 31, 1979
LP&L Letter, LPL 13322 dated March 14, 1980

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(e), we are hereby providing two copies of the Final Report of Significant Construction Deficiency No. 6, "Emergency Diesel Generators-Defective Shafts & Springs" and two copies of the Final Report of Significant Construction Deficiency No. 10, "Defective Emergency Diesel Generator Roller Pins."

If you have any questions, please advise.

Very truly yours,

D. L. Aswell

D. L. Aswell

DLA/LLB/grf

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
(with 15 copies of each report)

S 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2019
S
1/1

800929094