

## LICENSEE EVENT REPORT

CONTROL BLOCK:  (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T REPORT SOURCE | L 6 0 5 0 0 | 0 3 3 5 7 | 1 2 1 3 1 8 1 2 3 | 0 1 1 0 1 8 3 9 |

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES**

During normal full power operation while performing surveillance testing, the A train containment spray flow control valve (FCV 07-1A) would not open fully. Action was taken in accordance with Tech Specs 3.6.2.1 and 3.6.2.2 and the system restored to operability well within the required time. The health and safety of the public were not affected. LER 77-034 also involved containment spray inoperability.

0 3 | \_\_\_\_\_ J

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE		REVISION NO.																											
0	9	S	B	(11)	E	(12)	B	(13)	V	A	L	V	E	I	X	(14)	X	(15)	X	(16)	(0)																				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	
LEADING REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		COMPONENT MANUFACTURER																															
(17)	REPORT NUMBER	8	2	21	22	23	24	0	6	5	27	1	0	1	3	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SIC		ATTACHMENT SUBMITTED		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER																													
A	(18)	Z	(19)	Z	(20)	MANUFACTURER	(21)	HOURS	(22)	N	(23)	N	(24)	A	(25)	A	6	1	0	(26)	(27)	(28)	(29)	(30)	(31)	(32)	(33)	(34)	(35)	(36)	(37)	(38)	(39)	(40)	(41)	(42)	(43)	(44)	(45)	(46)	(47)

**CAUSE DESCRIPTION AND CORRECTIVE ACTIONS**

10 The solenoid operated air control valve for FCV 07-1A had failed mechanically  
 11 and was replaced. The surveillance testing was completed satisfactorily  
 12 and A train containment spray was returned to operable status.

1 3

1 4  
7 8 9

FACILITY STATUS % POWER OTHER STATUS (3) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (62)  
Surveillance Test

ACTIVITY CONTENT  
RELEASED OR RELEASED  
AMOUNT OF ACTIVITY (35)  
LOCATION OF RELEASE (36)

**NA**

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
PERSONNEL EXPOSURES  
NUMBER TYPE DESCRIPTION

1 7 0 0 0 17 Z 08 NA

1 2 3 4 5 6 7 8 9 10 11 12 13 14  
PERSONNEL INJURIES  
NUMBER DESCRIPTION 41

**1 3** **0 0 0** **40** **NA**

LOSS OF OR DAMAGE TO FACILITY **43**  
TYPE DESCRIPTION

1 9 Z 41 NA

PUBLICITY  
DESCRIPTION 55

20 N 42 NA

S. Laur (305) 465-3426

NAME OF APPLICANT \_\_\_\_\_ PHONE \_\_\_\_\_

180316 830110  
A0000 05000225

ADUCK 09000339  
PDR

8301180316 830110  
PDR ADOCK 05000335  
S PDR