

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37402
400 Chestnut Street, Tower II

October 10, 1980

50-328

~~Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20585
101 Independence Street
Washington, D.C. 20585~~

50-328J

Dear Mr. O'Reilly:

EDWARDSON NUCLEAR PLANT UNIT 2 - INCORRECT INSULATION WEIGHT USED IN PIPING
ANALYSIS - NRC GEN CDR 5009 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-CID Inspector
John H. McFarland on April 24, 1980, in accordance with 10 CFR 50.55(e).
An interim report was submitted on May 23, 1980. We expect to submit
our next report by January 12, 1981.

TVA is reviewing the as-construted insulation drawings for unit 2 as they
are received. Any discrepancies will be evaluated to determine if any
analysis analysis is affected.

If you have any questions, please get in touch with D. L. Lambert at
(615) 387-42581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. W. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20585

B0 9
S. 10

S

5010210 560