



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

January 12, 1983

RICHARD C DE YOUNG DIRECTOR
OFFICE OF INSPECTION & ENFORCEMENT
U S NUCLEAR REGULATORY COMMISSION
WASHINGTON D C 20555

DOCKET 50-312
RANCHO SECO NUCLEAR GENERATING STATION
UNIT NO 1
IE BULLETIN NO 82-04

IE Bulletin No. 82-04, dated December 3, 1982, identified deficiencies in primary containment electrical penetration assemblies and asked us to review the information for applicability to Rancho Seco.

The electrical penetration assemblies that were identified in the Bulletin were supplied by Bunker Ramo Company. The containment electrical penetration assemblies installed at Rancho Seco were supplied by Conax, thus this Bulletin is not applicable to Rancho Seco.

John J. Mattimoe
John J. Mattimoe
General Manager

IE11

B301180351 B30112
PDR ADOCK 05000312
Q PDR