


VERMONT YANKEE NUCLEAR POWER CORPORATION



RD 5, Box 169, Ferry Road, Brattleboro, VT 05301

2.C.2.1
FVY 83-2

REPLY TO
ENGINEERING OFFICE

1671 WORCESTER ROAD
FRAMINGHAM, MASSACHUSETTS 01701
TELEPHONE 617-872-8100

January 10, 1983

U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
Region I
631 Park Avenue
King of Prussia, PA 19406

Attention: Mr. Ronald C. Haynes, Regional Administrator

References: a) License No. DPR-28 (Pocket 50-271)
b) USNRC, IE Bulletin 82-04, dated December 3, 1982;
Deficiencies in Primary Containment Electrical Penetration
Assemblies

Dear Sir:

Subject: Response to IE Bulletin No. 82-04

We have no Bunker Ramo electrical penetrations in use at Vermont Yankee nor do we plan to install any in safety related systems in the future.

We trust that you will find this response satisfactory; however, should you desire any additional information, do not hesitate to contact us.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

Warren P. Murphy
Warren P. Murphy
Vice President and
Manager of Operations

IE11

WPM/dm

8301180369 830110
PDR ADCK 05000271
G PDR

