

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

January 24, 1983

U.S. Nuclear Regulatory Commission  
Region II  
ATTN: James P. O'Reilly, Regional Administrator  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-07 -  
RII:JPO 50-259, -260, -296 - BROWNS FERRY NUCLEAR PLANT

This letter is to inform you that all 20 jet pump beam holddown bolt assemblies on Browns Ferry Nuclear Plant unit 2 have been replaced with improved assemblies. General Electric Company report NEDE-24362-1 shows that the service life of the improved assemblies will exceed the remaining service life of Browns Ferry unit 2. Because of this we do not consider IE Bulletin 80-07 as applicable to unit 2 any longer. Therefore, we will discontinue performing the inspection required by that bulletin. If you have any questions, please call Jim Domer at FTS 858-2725.

To the best of my knowledge, I declare that statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*D S Kammer*

D. S. Kammer  
Nuclear Engineer

cc: Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

8302150047 830124  
PDR ADOCK 05000260  
Q PDR