The University of Michigan Radiation Control Service 1101 North University Building Ann Arbor, MI 48109	2. REGIONAL OFFICE Region III
Aim Arbor, HI 40105	799 Roosevelt Road Glen Ellyn, IL 60137
	21-00215-04;-05 5. DATE OF INSPECTION ;-1835;SUD-1398 24 - 28 January, 1983
Licensee :	
The inspection was an examination of the activities conducted under your lices. Regulatory Commission's (NRC) rules and regulations and the conditions of your depresentative records, interviews, with personnel, and observations by the	our license. The inspection consisted of selective examinations of procedures
X 1 Within the scope of this inspection, no violations were observed.	
2. The inspector also verified the steps you have taken to correct the violate those actions at this time.  3. During this inspection certain of your activities, as checked below, were THIS IS A NOTICE OF VIOLATION which is required to be posted in	ation of NRC requirements.
of a	was not properly posted to indicate the presence 10 CFR 20.203(b), (c), (d), (e) or 34.42
01.8	. 10 0111 20.203(0), (c), (d), (e) 01 34.42
B. Containers located in	were not properly
labeled to indicate the presence of radioactive material. 10 CFR 20.	203(f)(1), or (f)(2).
	of sealed sources were not performed at the proper
frequencies 10 CFR	License Condition Number
D. Records of	or License Condition Number
E. Documents were not properly posted or otherwise made available. 1	0 CFR 19.11.
F. Reports or notifications of	we ot made in accordance
with 10 CFR	or License Condition Number
H	
417	
1	
<i>t</i>	
8302150126_830128_	IE HA File Och
LIK. PDR ADOCK 04008787	5012 15 57 PM
hereby state that within 30 days the actions described by me to the inspector	DIVID 1E-01 V

Charles Grandenergers Vice President 128/83

James R. Mullauer
SIGNATURE - NRC INSTECTOR

1/28/83 DATE