Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY STATION MANAGER

January 31, 1983



TELEPHONE (714) 492-7700

U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596-5368

Attention:

Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-362

30-Day Report

Licensee Event Report No. 82-010

San Onofre Nuclear Generating Station, Unit 3

Pursuant to Section 6.9.1.13.b of Appendix A Technical Specifications to Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required 30-day report for an occurrence involving inoperable fire detection instrumentation.

Prior to issuance of the San Onofre Unit 3 low power license, fire watches were established for fire detection instrumentation which was expected to be inoperable at the time of license issuance and, with license issuance, would require fire watches pursuant to Action Statement 'a' of LCO 3.3.3.7. Such fire watches were established on November 11, 1982 for Zones 1, 9 and 28. As a result of these fire watches being established before they were specifically required, they were not recognized, until recently, as requiring a 30-day report. This letter represents a delayed 30-day report.

Completion of operability testing in accordance with Technical Specification Surveillance Requirement 4.3.3.7.1 has not yet been completed for fire detection instrumentation in these areas and, therefore, the affected detectors have not yet been declared operable. We expect testing to be completed within 90 days. The fire watches will continue until the detectors are declared operable. The associated spray/sprinkler systems have remained operable throughout this period.

Since delay in the submittal of this report was caused by circumstances unique to the initial licensing of Unit 3 and 30-day reports are now being initiated as a result of establishment of fire watches, no further corrective action is planned.

- cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Units 2 & 3)
  - R. J. Pate (USNRC Resident Inspector, San Gnofre Units 2 & 3)
  - U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement
  - U. S. Nuclear Regulatory Commission Office of Management Information and Program Control

Institute of Nuclear Power Operations