

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

January 24, 1983

Mr. James J. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:JPO
Catawba Nuclear Station
Docket Nos. 50-413 and 50-414

Dear Mr. O'Reilly:

In response to IE Bulletin 82-04 concerning deficiencies in primary containment electrical penetrations, please be advised that no Bunker Ramo electrical penetrations are installed or are planned to be installed in safety-related systems at the Catawba Nuclear Station. This bulletin took approximately two man-hours to investigate and respond to.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge.

Very truly yours,

HAL B. TUCKER

Hal B. Tucker

RWO/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. P. K. Van Doorn
NRC Resident Inspector
Catawba Nuclear Station

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

8302150219 830124
PDR ADOCK 05000413
Q PDR

IE11