

APPENDIX A
NOTICE OF VIOLATION

Tennessee Valley Authority
Sequoyah Unit 1

Docket No. 50-327
License No. DPR-77

As a result of the inspection conducted on September 6 - October 5, 1982 and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 3.6.1.8 requires that two independent Emergency Gas Treatment System (EGTS) cleanup subsystems shall be operable in modes 1, 2, 3 and 4.

Contrary to the above, two EGTS cleanup subsystems were not maintained operable in that on September 11, 1982 the Unit 1 elevation 690 annulus door was left open and obstructed by test equipment when the Unit was in mode 3 (450°F). With the annulus door open the EGTS would not have been able to maintain the required negative pressure in the annulus for operability. The licensee identified the violation and took immediate action to close the annulus door and return the EGTS to an operable status.

This is a Severity Level IV Violation (Supplement I.D.2). This violation applies to Unit 1 only.

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: NOV 30 1982