

SAFETY INSPECTION

1. LICENSEE Nondestructive Inspection Services, Inc P.O. Box 220 Hurricane, West Virginia 25526		2. REGIONAL OFFICE REGION II U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323	
3. DOCKET NUMBER(S) 030-06695	4. LICENSE NUMBER(S) 47-11883-01	5. DATE OF INSPECTION 1/13/94	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.
 - A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b),(c),(d),(e) or 34.42.
 - B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____.
 - C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.
 - D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
 - E. Reports or notification of 9403250187 940121
PDR ADOCK 03006695
C PDR _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
 - F. Shipping paper accompanying radioactive material during transport did not include the hazard class as part of the proper shipping name (9 CFR 172.202 (a)(2))

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective action is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE <u>H. M. [Signature]</u>	DATE <u>25007</u>	SIGNATURE - NRC INSPECTOR <u>[Signature]</u>	DATE <u>1/21/94</u>
--	----------------------	---	------------------------

IEO7

SAFETY INSPECTION

1. LICENSEE Nondestructive Inspection Service, Inc P.O. box 220 Hurricane, West Virginia 25526		2. REGIONAL OFFICE REGION II U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323		
3. DOCKET NUMBER(S) 030-06695	4. LICENSE NUMBER(S) 47-11883-01	5. DATE OF INSPECTION 1/13/94		

3. (Continued)

G. Sealed source containing 0.5 millicurie of ⁶⁰Co was shipped on 1/6/94 and the shipping paper did not contain the proper shipping name (176 302 (alt))

H. Licensee failed to verify by an acceptable method that the transporter's specific license authorized receipt of this type, form and quantity prior to transfer at 31 ALE 520 Express Service containing 27 lbs of ⁶⁰Co (100030 7/11)

I. Licensee failed to include with the packing list enclosed as a note to be marked on the package a statement conveying the information required by 49 CFR 173.421-1 when shipping empty radioactive drums

4. The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

A. _____

B. _____

C. _____

IE07