Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-295 Docket No. 50-304

As a result of the ins, ction conducted on December 6-16, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

Technical Specification 6.2.A states, in part: "Detailed written procedures including checkoff lists covering items listed below shall be prepared, approved, and adhered to:...7. Surveillance and testing requirements..."

Technical Specification 4.3.6.B lists the following surveillance requirement: "Measurement of EBAR will be performed at least twice monthly."

Contrary to the above, the licensee has not approved procedure for the determination of EBAR.

This is a Severity Level V violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

an 12, 1981

alfind

J A. Hind, Director Division of Emergency Preparedness and Operational Support