

SEP 1 1982

Dayton X-Ray Company
ATTN: R. W. Sammons
President
1150 West Second Street
Dayton, OH 45407

License No. 34-06943-01

34-573 L

Gentlemen:

This refers to the routine safety inspection conducted by S. R. Lasuk of this office on August 16-18, 1982, of activities authorized by NRC Byproduct Material License No. 34-06943-01 and to the discussion of our findings with Mr. R. J. Sammons at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated December 21, 1981, regarding apparent items of noncompliance found during our investigation and inspections conducted during the period October 20, 1980 - March 2, 1981, and September 22-23, 1981. We have no further questions regarding these matters at this time.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

for
D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

cc: DMB/Document Control Desk (RIDS)

PIII
SLJ
Lasuk/jp
8/27/82

RIII
D.J. Sreniawski
Sreniawski
8/30/82

IE HQ FILE COPY

8209080069 820901
NMS LIC30
34-06943-01 PDR

DMB:IE07