

Appendix

NOTICE OF VIOLATION

Sheppard, Morgan and Schwaab, Inc.

License No. 12-20170-01

As a result of the inspection conducted on August 17, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 14A requires that you test your sealed sources containing byproduct materials for leakage and/or contamination at intervals not to exceed six months.


Contrary to the above, your Troxler surface moisture - density gauge was leak tested March 31, 1981 and January 26, 1982. This is a period in excess of the required six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

9-1-82

Dated



D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1